

Bruhath Bangalore Mahanagara Palike**Inspection Report**

1	Name of work	Providing CC road and Improvements to drain at 2nd A main in Bahubali nagara in Ward No.16
2	Administration Approval and Date	JC/RRNZ/AS/2501/2013-14, Date:30.10.2013
3	Technical Sanction Estimate No. & Date	EE/RRND/TS/202/2013-14, Date:30.10.2013
4	Estimate Amount	Rs.20.00 Lakhs
5	Job Code No	016-14-000014
6	P-Code	P-1771
7	Agreement No and Date	EE/RRND/Ag No./78/2014-15, Date:07.08.2014
8	Work order Number and Date	EE/RRND/WO No./78/2014-15, Date:07.08.2014
9	Contract Amount as per Agreement	Rs.20,98,293=00
10	Bill Amount	1st Bill - Rs.9,99,465=00 2nd Bill - Rs.10,98,830=00 Total - Rs.20,98,295=00
11	B.R No and Date	1st Bill - 72/2015-16, Date:30.04.2015 2nd Bill - 82/2015-16, Date:31.07.2015
12	Agency	Sri B. Raghavendra
13	M.B Number and Page No of Measurement records	3651/14-15, Page No.365010 to 365013 3651/14-15, Page No.365014 to 365018
14	Date of Inspection	03.09.2015
15	Enclosures	(1) Extract of MB No.3651, Page No.365018 (B) (2) 07 No. of photos taken during Inspection
16	Inspection Report	The above site has been inspected by me along with the concerned Engineer. The measurements have been checked by me for the items which are susceptible for measurements and found to be satisfactory.

EE (P) RR Nagara


(R.Sathyanaarayana)
Inspection Report officer